

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No. 12196

Approved For Release 2000/04/18 : DIA-RDP81B00879R00050080078-8

RECEIVED FROM

Plant #9

DATE REC'D 5-16-57

P.O. NO.

VENDOR PACKING SLIP NO.

O

R

ACCT. OR
W.O. NO.

S.O. NO.

CHARGE TO
QUANTITY
RECEIVEDCONTRACT
CODE NO. 322 DRAWING
NUMBER 000100 DWG.
STANDARD PART NO. 108 DWG.
REV. D LOT
NO. 10 CLASS
NUMBER 10 OPER.
NUMBER 10 BUY OUT
CODE NO. 10

DRAWING NO. AND DESCRIPTION

QUANTITY
ACCEPTED 4
REJECTED

REMARKS

4 731338

Insulator Contact

IN 7646

Mu Stor

RECEIVED
BYINSPECTED
BY

DATE 5-16-57

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVED FROM

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
244 E. COLORADO ST. PASADENA, CALIF.

No. 12197

DATE REC'D 5-16-57

P.O. NO.

VENDOR PACKING SLIP NO.

O

R

ACCT. OR
W.O. NO.

S.O. NO.

CHARGE TO
QUANTITY
RECEIVEDCONTRACT
CODE NO. 322 DRAWING
NUMBER 100100 DWG.
STANDARD PART NO. 037 DWG.
REV. D LOT
NO. 10 CLASS
NUMBER 10 OPER.
NUMBER 10 BUY OUT
CODE NO. 10

DRAWING NO. AND DESCRIPTION

QUANTITY
ACCEPTED 1
REJECTED

REMARKS

2 732392

Washer Revolving Cover

IN 7647

Mu Stor

RECEIVED
BYINSPECTED
BY

DATE

RETURNED
ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : DIA-RDP81B00879R00050080078-8